## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	3	(("6400058") or ("20030048029") or ("20030231451")).PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/06 13:18
<b>S</b> 2	82309	(noise transient interference) same (motor inductor load) same (suppress\$3 reduc\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 14:22
S3	45978	S2 same (DC motor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 14:23
S4	919	S2 same (DC adj motor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 14:23
\$5	36	S4 same high adj frequency	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 14:23
S6	88	S4 same capacitor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 15:19
S7	1	S6 same (varistor mov)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 15:20
S8	0	("2004/0114297").URPN.	USPAT	OR	ON	2008/08/06 15:22
S9	2	(("6078117") or ("5296771")).PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/06 15:27

S10	57	("2393045"   "3924147"   "4329605"   "4384223"   "4384331"   "4429241"   "4462012"   "4550268"   "4673837"   "4698605"   "4800348"   "4896067"   "4992060"   "5231321"   "5236376"   "5306974"   "5500629"   "5610467"   "5717270"   "5770902"   "5943214"   "5966684"). PN. OR ("6078117"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/06 15:28
S11	13	("4329605"   "4644804"   "4769566"   "4833357"   "4888511"   "5079468"). PN. OR ("5296771"). URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/06 15:36
S12	1901	(361/111).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/06 15:41
S13	1947	(361/111).OCLS.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/08/06 15:41
S14	421	S13 and (interference noise) and (suppress\$3 attenuta\$3 reduc\$3)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 15:42
S15	181	S14 and (high radio) near frequency	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 15:43
S16	76	S15 and capacitor and (Varistor mov)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 15:44
S17	3	S16 and (DC near motor)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/06 15:44

S18	349	((DC electric) near motor) with (carrier printed) near (plate board)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/07 16:22
S19	46	S18 and (noise spike transient)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/08/07 16:22
S20	84009	noise with filter	US-PGPUB; USPAT	OR	ON	2008/08/11 14:55
S21	13436	S20 same high adj frequency	US-PGPUB; USPAT	OR	ON	2008/08/11 14:55
S22	10749	noise near filter	US-PGPUB; USPAT	OR	ON	2008/08/11 14:55
S23	1123	S22 same high adj frequency	US-PGPUB; USPAT	OR	ON	2008/08/11 14:55
S24	1	S23 same DC adj motor	US-PGPUB; USPAT	OR	ON	2008/08/11 14:57
S25	57	S23 same motor	US-PGPUB; USPAT	OR	ON	2008/08/11 14:58
S26	7	("4316171"   "5008577"   "5196750"   "5296771"   "6078117"   "6285106"   "6300696").PN.	US-PGPUB; USPAT	OR	ON	2008/08/13 10:29
S27	1	("20070173086").PN.	US-PGPUB; USPAT; USOCR	OR	OFF	2008/08/13 10:36
S28	7	short adj circuit same (pointed narrow tapered) same (conductor connection) same (surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:32
S29	0	(short adj circuit near guard) same(pointed narrow tapered) same (conductor connection) same (surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:41
S30	0	(short adj circuit near guard) same(pointed narrow tapered) same (surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:41
S31	0	(short adj circuit near guard) same(surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:42

S32	203	(short adj circuit adj (guard protection rail)) same(surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:43
S33	0	(short adj circuit adj (guard protection rail)) same tapered same(surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:44
S34	2301	(short adj circuit adj (guard protection rail))	US-PGPUB; USPAT	OR	ON	2008/08/17 17:45
<b>S</b> 35	203	(short adj circuit adj (guard protection)) same (surge overvoltage transient)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:45
S36	0	S35 same (tapered narrow)	US-PGPUB; USPAT	OR	ON	2008/08/17 17:46
<b>S</b> 37	4	short adj circuit adj guard	US-PGPUB; USPAT	OR	ON	2008/08/17 18:02
S39	0	S38 same ((surge over \$1voltage transient) near (suppress protect))	US-PGPUB; USPAT	OR	ON	2008/08/17 18:12
S40	4	S38 same suppress	US-PGPUB; USPAT	OR	ON	2008/08/17 18:12
S41	236	(PCB (printed adj circuit)) same (via\$1hole)	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/17 18:16
S42	0	S41 same (DC motor)	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/17 18:25
S43	0	S41 same motor	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/17 18:25
S44	8	S41 and motor	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/17 18:25
S45	0	S41 and MCC	US-PGPUB; USPAT; USOCR	OR	ON	2008/08/17 18:27

8/17/2008 6:28:47 PM

C:\ Documents and Settings\ Ithomas1\ My Documents\ EAST\ Workspaces\ 10591890.wsp